INSPECTION REPORT

Name of work: Reconstruction of drain and providing covering slab in Mathrulayout in ward no 04

Est.Cost: Rs. 25.00 lakhs

Work Code: 004-15-000034

B.R No: 56, dt:29-06-2015

Bill amount: 2436584-00

Inspection Date: 26-02-2016.

Observations and conclusion:

The above said work Reconstruction of drain and providing Covering Slab in ~~mathr~~ mathru layout in ward no 04 was shown to me by the Concerned A.E.

The above work was inspected by me along with the Concerned Asst Engineer Sri Dayanand.

The work done is Satisfactory

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯೋಜನಾ ವಿಭಾಗ
ಜ.ಜ.ಎಂ.ಕ. ಬೆಂಗಳೂರು - 560064

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Name of Work :- Reconstruction of drain and providing covering slab in Mathrulayout in ward no 04.



INDEX :-

- Rcc Drain
- Rcc Culverts

Verified

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Name of Work :- **Reconstruction of drain and providing covering slab in Mathrlayout in ward no: 04**

AE

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT